

M2730\_01 **rauch**

3-4h

M2730

M2730

M2730



M2730

11x 	12x 6,3x50 	14x 8x30 	
4x 	36x 1,5x25 	7x 3x20 	
4x 3,5x15 	10x 	8x 6x8 	
4x M4x9 	4x 5,0x7,0 	4x 	12x Ø8 
6x 4x20 	3x 34x14,5x12 	4x 4x15 	
4x M6x40 	6x 		
6x 	9x 4,5x35 	12x 4x15 	

M2730

1	11	
---	----	--

1.

2.

3.

4.

**Xmm = Xmm**

**20 Min**

M2730

4x 	342x27x9,5
3x 	

M2730


2	4x 201 4x15 	4x 1 	
---	-----------------------	-------------	--

1.


2.

**SK010**  
**SK020**


M2730




M2730







M2730








M2730




M2730









M2730







M2730







M2730








M2730














M2730




M2730




M2730



M2730



M2730



M2730